

Einzelwerte:	1. 5.03	6. 5.01	11. 5.00	16. 5.00	21. 4.98	26. 4.98	31. 4.96	36. 4.94	41. 4.92	46. 4.98	51. 4.95	56. 4.97	61. 5.10	66. 5.11	71. 4.99	76. 5.11	81. 4.94	86. 5.00	91. 5.01	96. 4.97
	2. 4.95	7. 4.97	12. 5.04	17. 5.00	22. 5.01	27. 5.03	32. 5.09	37. 5.06	42. 5.08	47. 4.97	52. 5.05	57. 5.00	62. 4.98	67. 5.06	72. 4.99	77. 5.06	82. 5.07	87. 4.95	92. 5.02	97. 5.08
	3. 5.04	8. 5.00	13. 4.98	18. 5.05	23. 4.98	28. 5.04	33. 4.86	38. 5.01	43. 5.00	48. 5.02	53. 4.99	58. 5.09	63. 5.11	68. 4.99	73. 4.97	78. 4.98	83. 4.96	88. 5.02	93. 4.98	98. 5.04
	4. 5.00	9. 5.00	14. 4.97	19. 5.02	24. 4.96	29. 5.01	34. 4.94	39. 4.93	44. 4.96	49. 5.11	54. 5.00	59. 4.99	64. 5.02	69. 5.03	74. 5.00	79. 5.01	84. 5.02	89. 5.07	94. 4.99	99. 5.05
	5. 4.92	10. 5.01	15. 5.01	20. 4.99	25. 4.92	30. 4.98	35. 5.00	40. 4.97	45. 4.95	50. 4.93	55. 5.05	60. 5.13	65. 5.00	70. 5.10	75. 5.13	80. 4.99	85. 5.02	90. 4.98	95. 5.08	100. 4.98


# Kurvengrafik

Drehm.

5.04

Freq.

4000



Grenzfreq. 300 Hz

sec: 1.048, Nm: 2.40

Zoom

Restore

Laden

Speichern

Filter

Drucken

Ende

# Kurvengrafik

Drehm.


5.04

Winkel

718

Freq.

4000



Grenzfreq. 300 Hz

°: 1207.822, Nm: 2.40

Drehm.-Zeit



Drehm.-Winkel

Zoom

Restore

Laden

Speichern

Filter

Drucken

Ende