

Einzelwerte:	1. 2.99	6. 2.95	11. 2.97	16. 2.95	21. 2.91	26. 2.98	31. 2.95	36. 2.99	41. 2.92	46. 2.97	51. 2.91	56. 2.91	61. 2.91	66. 2.92	71. 2.93	76. 2.96	81. 2.91	86. 2.97	91. 2.98	96. 2.91
	2. 2.93	7. 2.97	12. 2.96	17. 2.91	22. 2.98	27. 2.94	32. 2.94	37. 2.91	42. 2.96	47. 2.94	52. 2.97	57. 2.96	62. 2.90	67. 2.92	72. 2.92	77. 2.97	82. 2.96	87. 2.97	92. 2.90	97. 2.96
	3. 2.93	8. 2.98	13. 2.97	18. 2.98	23. 2.92	28. 2.95	33. 2.96	38. 2.97	43. 2.94	48. 2.97	53. 2.92	58. 2.89	63. 2.95	68. 2.94	73. 2.96	78. 2.92	83. 2.94	88. 2.93	93. 2.92	98. 2.91
	4. 2.94	9. 2.93	14. 2.97	19. 2.90	24. 2.99	29. 2.94	34. 2.99	39. 2.90	44. 2.97	49. 2.97	54. 2.97	59. 2.96	64. 2.90	69. 2.93	74. 2.88	79. 2.92	84. 2.98	89. 2.97	94. 2.98	99. 2.97
	5. 2.94	10. 2.89	15. 2.93	20. 2.95	25. 2.93	30. 2.99	35. 2.93	40. 2.94	45. 2.90	50. 2.95	55. 2.94	60. 2.90	65. 2.97	70. 2.96	75. 2.96	80. 2.96	85. 2.96	90. 2.93	95. 2.97	100. 2.91


# Kurvengrafik

Drehm.

2.90

Freq.

4000



Grenzfreq. 300 Hz

sec: 0.597, Nm: 1.20

Zoom

Restore

Laden

Speichern

Filter

Drucken

Ende

# Kurvengrafik

Drehm.


2.90

Winkel

714

Freq.

4000



Grenzfreq. 300 Hz

°: 824.724, Nm: 1.20

Drehm.-Zeit



Drehm.-Winkel

Zoom

Restore

Laden

Speichern

Filter

Drucken

Ende