

Einzelwerte:	1. 1.67	6. 1.66	11. 1.73	16. 1.69	21. 1.71	26. 1.72	31. 1.71	36. 1.69	41. 1.71	46. 1.71	51. 1.70	56. 1.69	61. 1.70	66. 1.72	71. 1.72	76. 1.71	81. 1.75	86. 1.70	91. 1.68	96. 1.76
	2. 1.67	7. 1.71	12. 1.68	17. 1.73	22. 1.70	27. 1.71	32. 1.69	37. 1.71	42. 1.74	47. 1.64	52. 1.67	57. 1.67	62. 1.66	67. 1.72	72. 1.65	77. 1.69	82. 1.74	87. 1.70	92. 1.67	97. 1.75
	3. 1.67	8. 1.69	13. 1.69	18. 1.67	23. 1.70	28. 1.70	33. 1.73	38. 1.69	43. 1.69	48. 1.67	53. 1.72	58. 1.70	63. 1.72	68. 1.65	73. 1.66	78. 1.72	83. 1.65	88. 1.73	93. 1.77	98. 1.70
	4. 1.67	9. 1.69	14. 1.71	19. 1.70	24. 1.68	29. 1.75	34. 1.67	39. 1.68	44. 1.74	49. 1.72	54. 1.64	59. 1.65	64. 1.66	69. 1.69	74. 1.67	79. 1.69	84. 1.69	89. 1.65	94. 1.70	99. 1.69
	5. 1.68	10. 1.70	15. 1.71	20. 1.69	25. 1.70	30. 1.68	35. 1.70	40. 1.73	45. 1.70	50. 1.71	55. 1.72	60. 1.68	65. 1.66	70. 1.73	75. 1.65	80. 1.65	85. 1.74	90. 1.72	95. 1.68	100. 1.72


# Kurvengrafik

Drehm.

1.69

Freq.

4000



Grenzfreq. 300 Hz

sec: 0.256, Nm: 0.61

Zoom

Restore

Laden

Speichern

Filter

Drucken

Ende

# Kurvengrafik

Drehm.


1.69

Winkel

29

Freq.

4000



Grenzfreq. 300 Hz

°: 68.704, Nm: 0.61

Drehm.-Zeit



Drehm.-Winkel

Zoom

Restore

Laden

Speichern

Filter

Drucken

Ende