

Einzelwerte:	1. 10.85	6. 10.91	11. 10.86	16. 10.91	21. 10.95	26. 11.02	31. 10.86	36. 10.99	41. 10.90	46. 10.83	51. 10.94	56. 10.91	61. 10.87	66. 10.99	71. 10.93	76. 10.91	81. 10.92	86. 11.02	91. 10.96	96. 10.94
	2. 10.96	7. 11.01	12. 10.91	17. 10.98	22. 10.96	27. 10.89	32. 10.99	37. 10.97	42. 10.91	47. 11.08	52. 10.98	57. 10.86	62. 10.81	67. 10.99	72. 10.91	77. 10.87	82. 10.92	87. 10.89	92. 10.95	97. 10.98
	3. 10.85	8. 10.86	13. 10.88	18. 10.96	23. 10.92	28. 10.95	33. 10.96	38. 10.98	43. 10.94	48. 10.88	53. 10.88	58. 10.94	63. 11.01	68. 11.03	73. 10.92	78. 10.96	83. 10.94	88. 10.96	93. 10.92	98. 10.92
	4. 10.94	9. 10.90	14. 10.97	19. 11.00	24. 10.88	29. 10.95	34. 10.97	39. 10.91	44. 10.94	49. 11.01	54. 10.89	59. 10.78	64. 10.95	69. 10.86	74. 11.05	79. 10.99	84. 10.88	89. 10.92	94. 10.84	99. 10.89
	5. 10.89	10. 10.85	15. 10.94	20. 10.97	25. 10.89	30. 10.99	35. 10.90	40. 10.93	45. 10.99	50. 10.91	55. 10.84	60. 10.91	65. 10.81	70. 10.83	75. 11.05	80. 10.95	85. 10.98	90. 10.91	95. 10.91	100. 10.91

Kurvengrafik

Drehm.


10.88

Winkel

726

Freq.

4000



Grenzfreq. 300 Hz

°: 490.686, Nm: 4.67

Drehm.-Zeit



Drehm.-Winkel

Zoom

Restore

Laden

Speichern

Filter

Drucken

Ende


Kurvengrafik

Drehm.

10.88

Freq.

4000



Grenzfreq. 300 Hz

sec: 0.639, Nm: 4.67

Zoom

Restore

Laden

Speichern

Filter

Drucken

Ende