

Einzelwerte:	1. 16.24	6. 16.05	11. 16.09	16. 15.83	21. 16.25	26. 15.94	31. 15.75	36. 16.17	41. 16.23	46. 15.45	51. 15.87	56. 15.59	61. 16.13	66. 16.16	71. 15.62	76. 15.80	81. 16.09	86. 15.92	91. 15.50	96. 15.61
	2. 16.02	7. 16.06	12. 16.15	17. 15.70	22. 15.82	27. 16.07	32. 16.10	37. 16.25	42. 15.90	47. 15.48	52. 15.76	57. 15.95	62. 15.66	67. 15.68	72. 16.19	77. 16.28	82. 15.99	87. 16.38	92. 15.83	97. 15.79
	3. 15.91	8. 15.71	13. 16.20	18. 15.50	23. 16.16	28. 16.21	33. 15.47	38. 15.85	43. 15.69	48. 15.82	53. 15.80	58. 15.75	63. 16.08	68. 15.78	73. 16.12	78. 15.55	83. 15.58	88. 15.83	93. 16.18	98. 15.95
	4. 16.07	9. 15.79	14. 16.05	19. 15.88	24. 15.75	29. 16.07	34. 16.04	39. 16.05	44. 15.73	49. 16.06	54. 15.46	59. 16.14	64. 15.61	69. 15.62	74. 15.98	79. 15.98	84. 15.75	89. 16.10	94. 16.08	99. 16.00
	5. 16.15	10. 16.15	15. 16.16	20. 16.29	25. 15.71	30. 16.19	35. 16.16	40. 15.52	45. 15.43	50. 15.82	55. 16.11	60. 15.59	65. 15.61	70. 15.98	75. 16.18	80. 15.42	85. 16.27	90. 15.94	95. 16.22	100. 15.78

Kurvengrafik

Drehmoment


16.18

Winkel

31

Freq.

2000



Grenzfreq. 300 Hz

°: 299.712, Nm: 8.58

Drehm.-Zeit



Drehm.-Winkel

Zoom

Restore

Laden

Sichern

Filter

Drucken

Ende

Kurvengrafik

Drehmoment


15.71

Winkel

28

Freq.

2000



Grenzfreq. 300 Hz

°: 300.594, Nm: 8.51

Drehm.-Zeit



Drehm.-Winkel

Zoom

Restore

Laden

Sichern

Filter

Drucken

Ende