

Einzelwerte:	1. 10.14	6. 9.96	11. 9.97	16. 9.94	21. 9.98	26. 10.05	31. 10.04	36. 9.87	41. 10.00	46. 9.88	51. 10.06	56. 9.98	61. 10.11	66. 10.00	71. 10.00	76. 10.08	81. 10.01	86. 9.91	91. 10.14	96. 9.89
	2. 10.09	7. 10.08	12. 10.02	17. 10.12	22. 10.13	27. 9.98	32. 10.04	37. 10.07	42. 9.92	47. 10.03	52. 9.98	57. 9.91	62. 9.94	67. 10.03	72. 10.08	77. 9.97	82. 9.88	87. 10.05	92. 10.02	97. 9.94
	3. 9.95	8. 10.03	13. 10.07	18. 10.02	23. 10.05	28. 10.02	33. 9.96	38. 9.97	43. 9.96	48. 10.03	53. 9.84	58. 10.12	63. 10.04	68. 10.01	73. 9.98	78. 9.91	83. 10.10	88. 10.00	93. 9.91	98. 9.91
	4. 9.95	9. 9.98	14. 10.01	19. 9.94	24. 9.88	29. 9.98	34. 9.98	39. 9.98	44. 10.09	49. 10.05	54. 9.97	59. 9.99	64. 9.98	69. 10.04	74. 9.91	79. 10.15	84. 9.95	89. 9.95	94. 10.03	99. 9.91
	5. 10.00	10. 10.13	15. 10.09	20. 10.11	25. 10.09	30. 10.08	35. 9.93	40. 10.02	45. 10.07	50. 9.94	55. 10.18	60. 9.98	65. 9.90	70. 10.04	75. 9.89	80. 10.04	85. 9.91	90. 10.10	95. 10.07	100. 10.10


# Kurvengrafik

Drehm.

9.87

Freq.

4000



Grenzfreq. 300 Hz

sec: 0.182, Nm: 4.95

Zoom

Restore

Laden

Speichern

Filter

Drucken

Ende

# Kurvengrafik

Drehm.


9.87

Winkel

31

Freq.

4000



Grenzfreq. 300 Hz

°: 49.748, Nm: 4.95

Drehm.-Zeit



Drehm.-Winkel

Zoom

Restore

Laden

Speichern

Filter

Drucken

Ende