

Einzelwerte:	1. 3.88	6. 3.80	11. 3.72	16. 3.81	21. 3.76	26. 3.81	31. 3.80	36. 3.73	41. 3.70	46. 3.80	51. 3.80	56. 3.75	61. 3.84	66. 3.74	71. 3.67	76. 3.80	81. 3.72	86. 3.78	91. 3.80	96. 3.73
	2. 3.84	7. 3.75	12. 3.74	17. 3.79	22. 3.82	27. 3.78	32. 3.86	37. 3.74	42. 3.74	47. 3.80	52. 3.72	57. 3.72	62. 3.83	67. 3.72	72. 3.75	77. 3.77	82. 3.77	87. 3.82	92. 3.73	97. 3.82
	3. 3.77	8. 3.77	13. 3.74	18. 3.77	23. 3.71	28. 3.79	33. 3.81	38. 3.75	43. 3.74	48. 3.71	53. 3.75	58. 3.77	63. 3.77	68. 3.74	73. 3.73	78. 3.74	83. 3.79	88. 3.80	93. 3.76	98. 3.68
	4. 3.85	9. 3.77	14. 3.72	19. 3.77	24. 3.74	29. 3.82	34. 3.77	39. 3.70	44. 3.66	49. 3.81	54. 3.77	59. 3.80	64. 3.81	69. 3.73	74. 3.80	79. 3.72	84. 3.77	89. 3.82	94. 3.69	99. 3.78
	5. 3.82	10. 3.79	15. 3.73	20. 3.84	25. 3.84	30. 3.83	35. 3.84	40. 3.75	45. 3.81	50. 3.82	55. 3.85	60. 3.75	65. 3.75	70. 3.76	75. 3.72	80. 3.80	85. 3.81	90. 3.79	95. 3.73	100. 3.76


Kurvengrafik

Drehmoment

3.81

Freq.

2000



Grenzfreq. 300 Hz

msec: 140.322, Nm: 2.10

Zoom

Restore

Laden

Sichern

Filter

Drucken

Ende

Kurvengrafik

Drehmoment


3.81

Winkel

60

Freq.

2000



Grenzfreq. 300 Hz

°: 331.502, Nm: 2.10

Drehm.-Zeit



Drehm.-Winkel

Zoom

Restore

Laden

Sichern

Filter

Drucken

Ende