

Einzelwerte:	1. 60.70	6. 58.90	11. 59.61	16. 59.27	21. 58.52	26. 59.92	31. 59.30	36. 59.57	41. 58.08	46. 58.81	51. 57.40	56. 58.27	61. 58.67	66. 58.27	71. 57.92	76. 57.51	81. 57.42	86. 58.70	91. 58.01	96. 57.37
	2. 60.14	7. 60.05	12. 59.36	17. 59.95	22. 58.33	27. 60.01	32. 58.21	37. 60.15	42. 59.36	47. 59.08	52. 58.37	57. 57.61	62. 58.65	67. 58.17	72. 58.11	77. 57.62	82. 58.54	87. 58.30	92. 58.37	97. 57.56
	3. 59.36	8. 60.64	13. 60.34	18. 59.90	23. 60.08	28. 58.58	33. 58.03	38. 58.41	43. 58.96	48. 59.05	53. 58.58	58. 58.51	63. 59.92	68. 58.40	73. 58.38	78. 58.49	83. 58.67	88. 58.00	93. 57.79	98. 57.44
	4. 57.97	9. 60.60	14. 58.53	19. 60.69	24. 59.70	29. 59.90	34. 59.57	39. 59.90	44. 58.93	49. 58.55	54. 59.20	59. 58.12	64. 59.53	69. 57.20	74. 58.98	79. 58.93	84. 57.74	89. 57.85	94. 58.37	99. 58.36
	5. 59.94	10. 58.60	15. 58.05	20. 59.69	25. 60.55	30. 58.94	35. 60.27	40. 59.52	45. 60.55	50. 58.50	55. 59.25	60. 58.62	65. 58.51	70. 58.94	75. 58.59	80. 57.68	85. 58.15	90. 59.16	95. 58.02	100. 58.46

Kurvengrafik

Drehmoment


60.55

Winkel

428

Freq.

2000



Grenzfreq. 300 Hz

°: 1039.764, Nm: 31.11

Drehm.-Zeit



Drehm.-Winkel

Zoom

Restore

Laden

Sichern

Filter

Drucken

Ende

Kurvengrafik

Drehmoment


58.59

Winkel

427

Freq.

2000



Grenzfreq. 300 Hz

°: 1001.648, Nm: 31.07

Drehm.-Zeit



Drehm.-Winkel

Zoom

Restore

Laden

Sichern

Filter

Drucken

Ende